


FITNESS CERTIFICATE

- 1 Name of Officer : Assistant Engineer, LSGD Section, Velloor Panchayath
- 2 Name of School : Bhavans Newsprint Vidyalaya, Velloor
- 3 Location with name of Education District : Kaduthuruthy, Kottayam
- 4 Period for which certificate issued : 2025 - 26
- 5 Classification of building
- Permanent building : Block 1- 1 floor
- : Block 2 - 2 floors
- : Block 3 - 2 floors
- : Block 4 - 1 floor
- 6 Nature of Defects, if any : Nil
- a Foundation and basement :
- b Superstructure :
- c Doors and windows :
- d Flooring :
- e Roof :
- f Misc :
- Any major defects noticed which will render the building unsafe in any manner
- 7 : No
- 8 Whether maintenance works have been done properly : Yes

9 Remarks

Certified that the School building was inspected by me on 13.10.2025. Scientific Technologies for examining the stability with reference to location, altitude, intensity of wind exposure, flood etc are not enforced in Engineering sections of Panchayaths. Hence only physical verification is done and in prima facie it is found that the class rooms stated above are sound as on date for conducting classes for the academic year 2025-26 strictly only under normal weather conditions. Sheet work used in the varandah of school building is of asbestos sheets. it should be removed as early as possible as per the direction of Government since it may cause severe health problems to students.

Place: Velloor



AP
23/10/25
Assistant Engineer
L.S.G.D Section
Velloor Grama Panchayat