

TO BE FILLED BY THE INSPECTING OFFICER

(Junior Engineer)

- 1 Name of the Officer Rakha Q Nair
- 2 Name of School Bhavan's Nests Point Vidyalyaya
Kadathurathy } Varkom
Wellore.
- 3 Location with Edn. Dist. I Sub Dist. Kadathurathy } Varkom
- 4 Classification of the building and size (basis for classification see Annexure 1)
 - i) Permanent (single or multi storied) ✓ Platti Shaged buildings
 - ii) Semi permanent
 - iii) Temporary shed
- 5 Period for which the certificate is issued 2020 - 21
- 6 Nature of defects, if any
 - a Foundation and basement
 - b Superstructure
 - c Doors and windows
 - d Woods work wrought and put up Nil
 - e Roof
 - f Flooring
 - g Misc. (Cracks etc.)
- 7 Any Major defects noticed which will render the building unsafe in any manner No
- 8 Whether maintenance works have been done properly Yes
- 9 Whether the structure is sound or not for conducting classes Structure is sound to work only at Normal Weather condition

- Note: 1. The stability of the structure should be examined also with reference to location, attitude intensity of wind exposure flood etc.
2. Any additional observations if deemed necessary for the certificate may be furnished separately with the certificate.

Certified that the School was inspected by me on 22.6.20 and found to be fit to conduct for the period June 2020 to March 2021

Place Wellore

Signature :

[Signature]

Designation:

Assistant Engineer
I.S.G.E.
Vellore (C.E.)

Date : 22/6/20

